

Serial No. 10/566,484
Response to Office Action
Replacement Sheet

The diagram illustrates a mechanical linkage system, possibly for a prosthetic arm. Key components and labels include:

- 10**: A large, curved structural member or housing.
- 11**: A link or arm segment.
- 13**: A component at the base, possibly a pivot or support.
- 20**: A component at the bottom left, possibly a base or support structure.
- 21**: A component at the top, possibly a gripper or end effector.
- W**: A point of connection or joint.
- X**: A point of connection or joint.
- Y**: A point of connection or joint.
- L1**: A point of connection or joint.
- L2**: A point of connection or joint.
- INCLINED ANGLE**: A specific angle indicated by dashed lines and arrows, likely defining the orientation of a link.

The diagram shows the assembly of these components, with various joints (indicated by circles) and dashed lines representing the movement or alignment of the parts.